

Photo 1: 0 Algonquin Road, Sudbury View of Rockwood Drive street line facing southeast from corner File 751-6/22-009 Photography: September 29, 2022



Photo 2: 0 Algonquin Road, Sudbury View of Algonquin Road street line facing east from corner File 751-6/22-009 Photography: September 29, 2022



Photo 3: 0 Algonquin Road, Sudbury Drainage channel and box culvert on Algonquin Road File 751-6/22-009 Photography: September 29, 2022



Photo 4: 0 Algonquin Road, Sudbury Drainage easement along easterly limit of subject land File 751-6/22-009 Photography: September 29, 2022



Photo 5: Rockwood Drive, Sudbury

Low density housing located opposite subject land on west side of Rockwood Drive File 751-6/22-009 Photography: September 29, 2022



Photo 6: Rockwood Drive, Sudbury Low density housing on Greenvalley Drive at intersection with Rockwood Drive File 751-6/22-009 Photography: September 29, 2022



Photo 7: Rockwood Drive, Sudbury Bell Canada building abutting directly south of subject land File 751-6/22-009 Photography: September 29, 2022



Photo 8: 2650 Algonquin Road, Sudbury Algonquin Road Public School located north of subject land File 751-6/22-009 Photography: September 29, 2022



Photo 9: Vintage Way, Sudbury Single detached dwellings on Vintage Way directly abutting easterly limit of subject land File 751-6/22-009 Photography: September 29, 2022



Photo 10: 47 & 54 Vintage Way, Sudbury View from Vintage Way facing southwest towards subject land File 751-6/22-009 Photography: September 29, 2022



Photo 11: 50 Cognac Court, Sudbury Single detached dwelling on Cognac Court directly abutting easterly limit of subject land File 751-6/22-009 Photography: September 29, 2022



Photo 12: 50 & 54 Cognac Court, Sudbury View from Cognac Court facing northwest towards subject land File 751-6/22-009 Photography: September 29, 2022



Photo 13: Algonquin Road, Sudbury Informal access onto site facing west File 751-6/22-009 Photography: September 29, 2022



Photo 14: Algonquin Road, Sudbury Interior view illustrating typical conditions File 751-6/22-009 Photography: September 29, 2022



Photo 15: Algonquin Road, Sudbury

Interior view facing northeast of proposed vegetative buffer with white birch predominant File 751-6/22-009 Photography: September 29, 2022



Photo 16: Algonquin Road, Sudbury Interior view facing east of proposed vegetative buffer with trembling aspen predominant mixed with white birch File 751-6/22-009 Photography: September 29, 2022