


Traffic Control – Buckingham Drive and Fairmount Drive

Background

The Transportation and Innovation Services section has received a request to review the traffic control at the intersection of Buckingham Drive and Fairmount Drive in New Sudbury.



Fairmount Drive intersects Buckingham Drive forming a “T” intersection. Currently, the intersection is controlled by a Stop sign facing northbound traffic on Fairmount Drive. Traffic volumes are low at this intersection with adequate sight lines in all directions. A Yield sign is appropriate when the traffic volume is low, sight lines are good and stopping is not always

required. It is recommended that the existing Stop sign be changed to a Yield sign facing northbound traffic on Fairmount Drive.