

City Of Greater Sudbury Quarterly Report On AG Audit Results

Change To Audit Protocol For Audit Follow Up Reporting

August 13, 2013

Change To Audit Protocol For Audit Follow Up Reporting



		Status Of Action Plans - Follow Up Approach	Past Approach	Updated Approach
	1.	 Self-Assessment Follow Up A self assessment by program managers. The Auditor General's Office will send a self-assessment form to program managers The Auditor General will allow divisional staff two weeks to provide comments on the self assessment form. Management will be able to describe the progress that they have made in implementing the Auditor General's Office recommendations and their plans going forward. Management's self assessment will then be published unedited and in their entirety. 		
	2.	 Subsequent Self-Assessment Follow up Published within one year of the initial follow-up Subsequent follow-ups will also be unedited self-assessments provided by management. The Auditor General will allow divisional staff two weeks to provide comments on the self assessment form. 		
	3.	 Progress Assessments The Auditor General's Office will assess the organization's self-assessment of all or selected recommendations to confirm their reliability. The results of progress assessments will be published in the next follow up report. 		
	4.	 Progress Audits Audit level assurance will be provided as to the validity of the entity's self-assessments. This will involve conducting the entire audit again. Given the resources required to complete this form of assessment, the Office has yet to conduct work of this nature and would do so only when prudent. 		2

Change To Audit Protocol For Audit Follow Up Reporting



	Roads - Impact Of Changes To Road Design			
	Audit Report Released	August 2012		
	Original # Of Recommendations	13		
E	# Of Action Plans Now Closed	10		
	# Of Action Plans On Next Followup			
	Status As Of June 30, 2013	On Track	STATUS OF OVERALL RESPONSE • Closed • On Track • Some Delays • Not Addressed	
	Recommendation and Summary Of Progress	Self-assessed		
	(Note: Self assessment conducted by Roads Division)	Status		
	Recommendation 1			
A	The City should improve policies, procedures and reports supporting accountability for	Partially Implemented	STATUS OF SPECIFIC	
	rejection of inferior products and enhanced follow-up on warranty issues.	ACTION PLAN • Fully or Substantially Implemented • Alternative Action Taken • Partially Implemented • No Substantial Action Taken		
Μ	Original Management Response Will formulate reporting procedure for test results. This can be completed within six mont			
PL	Actions taken, results and /or actions planned			
	All test results are reported to the Chief Field Inspector for distribution. As a result of disc annual contractor's meeting there was subsequent committees comprised of staff and cor address a variety of issues, including developing a formal procedure for warranty issues.			
F	Recommendation 2			
	The City should further investigate rejectable materials from previous and current projects, and establish appropriate remedies where warranty provisions allow.	Fully or Substantially Implemented		
	Original Management Response Will monitor and continue to monitor areas already identified and determine corrective m been implemented.			
	Actions taken, results and /or actions planned			
AUDITOR GENERAL	Staff continue to monitor areas already identified and determine corrective measures. A f procedure is being developed by a committee comprised of staff and contractors.	3		