



Photo 1. Subject lands looking south showing the access driveway extending from Bancroft Drive to the lift station located to the rear of the property. CGS Files #751-6/21-25 and #751-6/21001



Photo 2. Lift station and elevated rail line located to the rear of the property, looking southwest. CGS Files #751-6/21-25 and #751-6/21001



Photo 3. Subject lands looking north from the rear of the property towards Bancroft Drive. CGS Files #751-6/21-25 and #751-6/21001



Photo 4. Residential use fronting onto the south side of Bancroft Drive, located to the west of the subject lands, looking southwest. CGS Files #751-6/21-25 and #751-6/21001



Photo 5. Residential use fronting onto the north side of Bancroft Drive, located to the north of the subject lands, looking northeast. CGS Files #751-6/21-25 and #751-6/21001



Photo 6. Residential use fronting onto the south side of Bancroft Drive, located to the east of the subject lands, looking southeast. CGS Files #751-6/21-25 and #751-6/21001



Photo 7. Residential use fronting onto the north side of Bancroft Drive, located to the north of the subject lands, looking northwest. CGS Files #751-6/21-25 and #751-6/21001