



Photo 1: 1830 Yorkshire Drive, Val Caron
Single detached dwelling to be severed from parent parcel
File 751-7/19-1 Photography May 17, 2019



Photo 2: 1830 Yorkshire Drive, Val Caron
New culvert providing drainage southerly under Yorkshire Drive
File 751-7/19-1 Photography May 17, 2019



Photo 3: 1830 Yorkshire Drive, Val Caron
Location of proposed new driveway providing access to northerly lands
File 751-7/19-1 Photography May 17, 2019



Photo 4: 1830 Yorkshire Drive, Val Caron
Drainage course along westerly limit of property
File 751-7/19-1 Photography May 17, 2019



Photo 5: 1830 Yorkshire Drive, Val Caron
Evidence of site alteration within regulated area
File 751-7/19-1 Photography May 17, 2019



Photo 6: 1830 Yorkshire Drive, Val Caron
Typical conditions north of existing dwelling (vicinity of proposed new dwelling)
File 751-7/19-1 Photography May 17, 2019