



Photo 1: Deschene Road, Hanmer
View of subject property from Deschene Road street line
File 751-7/20-07 Photography Sept 24, 2020



Photo 2: Deschene Road, Hanmer
Vacant commercial land abutting southerly with retail use located further south
File 751-7/20-07 Photography Sept 24, 2020



Photo 3: Deschene Road, Hanmer
Grocery store on east side of Deschene Road opposite subject land
File 751-7/20-07 Photography Sept 24, 2020



Photo 4: Philippe Street, Hanmer
Interior view of subject property showing typical conditions
File 751-7/20-07 Photography Sept 24, 2020



Photo 5: Philippe Street, Hanmer
View of existing turnaround at north end of Philippe Street
File 751-7/20-07 Photography Sept 24, 2020



Photo 6: Philippe Street, Hanmer
Existing conditions between south limit of subject land and abutting single detached dwelling on west side of Philippe Street
File 751-7/20-07 Photography Sept 24, 2020



Photo 7: Philippe Street, Hanmer
Existing conditions between south limit of subject land and abutting single detached dwelling on east side of Philippe Street
File 751-7/20-07 Photography Sept 24, 2020